

2780 Highland Ave Norwood, OH 45212

Job Title: Machinist

Job Summary

Operate various machine tools to manufacture and repair mechanical assemblies.

Qualifications

Preferred minimum level of education: High School Diploma, plus some high school, trade school, vocational/technical school, military, or on-the-job machine shop training.

Special Skills

Basic mechanical aptitude.

Ability to understand, perform and retain various job-related training and operational and safety procedures demonstrated by supervisor.

Ability to work well with others in a team effort.

Physical Abilities

To perform this job successfully an individual must be able to:

- Frequently lift and/or move up to 50 pounds; talk or hear.
- Regularly lift and/or move up to 25 pounds; stand; walk; use hands to finger, handle, or feel and reach with hands and arms.
- Occasionally lift more than 100 pounds; climb or balance and stoop, kneel, crawl, or crouch.
- Clearly see 20+ feet with or without corrective lenses. Have ability for close vision, distance, vision, peripheral vision, depth perception and ability to adjust focus.

Work Preformed

- Record all data necessary to produce expected service and/ or design results, including sizing and illustrations
- Use measuring devices, such as calipers and micrometers, and techniques correctly to assure proper sizing.

- Perform milling operations such as drilling, tapping, boring, and conventional milling and lathe work, using various engine lathes.
- Perform various metalizing techniques as needed.
- Understand materials and applications as required.
- Perform various welding operations, including setup and use of MIG, TIG, torch and stick welders.
- Set up and perform tool operations, such as broaching procedures, bearing work, and undercutting.
- Use various hand-held and stationary power and non-power tools, including but not limited to: band saws, belt sanders, hand grinders, files, etc.
- Lift, tighten, adjust and / or secure heavy objects in order to perform work and/ or to observe safety precautions.
- Observe all safety procedures and use proper protective gear (especially eye and ear protection).
- Keep work area neat and clean.
- Assist other machinists in department with skilled or non-skilled duties.
- Assist other service center departments with skilled or non-skilled duties.
- Perform other skilled or non-skilled duties as directed.